


# POWERBUILT



## *Powertrain Transmission Component Lifters*



### PROBLEM

- \* *New model process with 8 areas requiring ergonomic lifters.*

### SOLUTION

- \* *4 unique lifters, two for each style of part.*

### ADDITIONAL INFO

- \* *Zero G circuitry with no up-down pendants.*
- \* *Pneumatic clamping with manual rotation.*
- \* *Locate touch down pad used on differential assist.*

LEARN MORE AT [POWERBUILT.NET](http://POWERBUILT.NET)

### CONTACT US:

PowerBuilt Material Handling Solutions, LLC  
(937) 592-5660  
[Solutions@PowerBuilt.net](mailto:Solutions@PowerBuilt.net)