





POWERBUILT



Doors Off Carts



PROBLEM

- * *New line layout*
- * *(4) models*
- * *No room for overhead system*

- * *(2) back up carts supplied*
- * *Urethane tough points*
- * *Powered up/down, clamp, tilt, roll*

SOLUTION

- * *(4) mobile carts*
- * *Pneumatic controls*
- * *Rough locate at pick up*

LEARN MORE AT POWERBUILT.NET

CONTACT US:

PowerBuilt Material Handling Solutions, LLC
(937) 592-5660
Solutions@PowerBuilt.net